



Case Study Emerald Princess and Grand Princess

Overview

Princess Cruise Lines, part of Carnival Corporation, carried out a dry dock refit in the Bahamas on the Emerald Princess and the Grand Princess vessels.



**PRINCESS
CRUISES®**

Project highlights

Name:	Princess Cruises
Location:	Dry dock
Project Type:	Stage refurbishment
Building Type:	Cruise Ship vessel
Product Types:	Harlequin Cascade
Stage Contractor:	Stage Technologies Ltd



HARLEQUIN
www.harlequinfloors.com

Case Study Emerald Princess and Grand Princess

The requirement:


Stage refurbishment and new stage surface.

The solution

The main stage refurbishment projects were carried out in conjunction with Stage Technologies Group.

The existing floor coverings were removed and defects in the plywood sub-floors were repaired. A latex screed with flexible smoothing compound was used to give a suitable finish before the installation of the Harlequin vinyl surfaces. In both cases Harlequin Cascade was permanently laid, with seams welded and silicone sealant applied to its perimeters, before PVC nosings were installed to the steps each side of the stage into the audience area.

Harlequin Cascade



If you would like further information, advice and samples please contact us on +61 9620 7770 or auscontact@harlequinfloors.com



HARLEQUIN
www.harlequinfloors.com